



NOTE: IF COPING CAP IS SPECIFIED TO NOT BE REMOVED, APPLY TRITOTROWEL BY BRUSH UNDER EXISTING FLANGE



TRITON

DTL: 2791
FACILITY

WALL FLASHING DETAIL
WITH COPING CAP REMOVAL
(NOT TO SCALE)

DETAIL NUMBER